


BMW Radio Pixel Repair Tool for E38 E39 E53

This tool is designed for repairing dead or fading pixels in BMW radios. It restores the radio display to its original clarity and is compatible with BMW radio models E38, E39, E53 and Range Rover models from 2003-2005.



Product Overview

Professional Pixel Repair Solution

This specialized ribbon cable is designed to address the common issue of disappearing pixels on BMW MID (Multi-Information Display) units. By replacing the faulty ribbon cable that connects the LCD display to the circuit board, this tool restores clarity to radio, telephone, and board computer messages. It provides a cost-effective alternative to complete unit replacement, essential for professional-grade repairs.

Compatibility

Compatible Vehicles

- 5 Series (E39) 1997-2003: 530, 528, 540, M5
- 7 Series (E38) 1997-2001: 740, 750
- X5 Series (E53) 1999-2006
- Range Rover 2003-2005

Order Details

| | |
|------------------------|-----------|
| Minimum Order Quantity | 10 pieces |
|------------------------|-----------|

Technical Details

| | |
|---------------------|---------------------------------------------------|
| Primary Application | MID Unit, LCD Display, Radio Unit, Board Computer |
|---------------------|---------------------------------------------------|