

BMW Instrument Cluster Pixel Repair Ribbon Cable

These pixel repair ribbon cables are designed for repairing pixel loss issues in BMW car instrument clusters. The cables replace damaged connections between the LCD screen and the circuit board, restoring clear and accurate display functionality.



ADDITIONAL IMAGES



Product Overview

Restoring Instrument Cluster Clarity

These flexible printed circuit ribbon cables are engineered to resolve common pixel loss issues in automotive instrument clusters. By replacing damaged or deteriorated connections, they restore full functionality and clarity to the display, ensuring critical driver information remains visible. This component is essential for professional automotive electronics repair, featuring precise contact points for reliable signal transmission.

Compatibility

Supported Vehicle Models

- 5 Series (E39) 1997-2003: 530, 528, 540, M5
- 7 Series (E38) 1997-2001: 740, 750
- X5 Series (E53) 1999-2006

Application

Instrument Cluster Repair, LCD Display Restoration, Automotive Electronics

Technical Details

Installation Requirement

Professional Installation Required • Specialized Tools Needed

Material Type

Flexible Printed Circuit (FPC)