


Analog Clamp Meter

This clamp meter measures AC current without breaking the circuit. It also includes test leads for measuring voltage and resistance.



Overview

Reliable Analog Measurement

This analog clamp meter offers a dependable solution for measuring AC current without the need to break the circuit. Designed for electrical maintenance and troubleshooting, it features a clamp for non-contact measurement and included test leads for precise voltage and resistance testing. The clear analog display ensures intuitive readings for professionals in various electrical work environments.

Technical Specifications

Measurement Functions	AC Current, Voltage, Resistance
Display Interface	Analog
Measurement Method	Non-contact clamp

Applications

Primary Applications

- Electrical maintenance
- Troubleshooting
- General electrical work